INSPECTION CONCLUSION DATA SHEET

Compliance Activity Type: Compliance Inspection

Compliance Monitoring Type: RCRA Hazardous & UST Compliance Evaluation Inspection (CEI)

Region: 10

Federal Statute: RCRA

Section: RCRA 9005

Compliance Monitoring Action Reason: Core Program

Compliance Monitoring Agency Type: EPA

Date of Inspection: 10/12/09

Inspector's Name: Phil Nenninger Phone No: (206) 553-4012

Compliance Monitoring Activity Name: Smitty's Conoco

EPA UST Facility ID No.: 4260087

Facility Street Address: 102 E. Toppenish Ave.

City: Toppenish

State: WA

Zip: 98948

Name of onsite representative at facility during inspection: Sue Smith

Date of Inspection: Begin: 10/12/09 End: 10/12/09

Indian Land: Yes

Tribally Owned: No

NAICS code: 447110: Convenience stores with gasoline stations

Number of days spent physically conducting the activity: 1 Number of hours spent physically conducting the activity: 1.5

Deficiencies:

Did you observe deficiencies (i.e. potential violations) during the inspection? Yes If yes, what deficiencies were observed? (Check one or more of the following deficiencies:)

| 사이 하면 생물하게 그렇게 하면 가게 되었다면 하는데 사용하게 되었다. 이 사람들은 내 내 내 그 아들이 되었다. 하는데 하는데 가게 다 가게 하는데 |
|---|
| Potential failure to complete or submit a notification, report, certification, or manifes |
| Potential failure to maintain a record or failure to disclose a document |

Potential failure to maintain a record or failure to disclose a document

Potential failure to maintain/inspect/repair meters, sensors, recording equipment

Potential failure to report regulated events such as spills, accidents, etc.

Potential failure to identify and manage a regulated waste or pollutant in any media

Potential violation of a compliance schedule in an enforcement order

Potential failure to obtain a permit, product approval, or certification

Potential incorrect use of material (pesticide, waste, product) or use of unapproved material

Potential failure to follow a permit condition(s)

Potential failure to follow a permit condition(s)

Potential failure to follow or develop a required management practice or procedure

Deficient management practice or procedure is defined as:

280.70(a) Failure to continue operation and maintenance of cathodic protection system in a temporarily closed tank system.

280.31(b)(1) Failure to ensure that cathodic protection system is tested within 6 months of installation. (Not RP)

Did you communicate these deficiencies to the facility during the inspection? Yes

Did you observe the facility take any actions during the inspection to address the deficiencies communicated to the facility? No

Page 1 of 2 Last revised: 03/10/2006

| Completed a notification or report |
|--|
| Corrected record keeping deficiencies |
| Corrected monitoring deficiencies |
| Verified compliance with previously issues enforcement action - part or all conditions |
| Implemented new or improved management practices or procedures |

Compliance Assistance:

Did you provide general compliance assistance in accordance with the policy on the Role of the EPA Inspector in Providing Compliance Assistance During Inspections? **Yes**

Did you provide site-specific compliance assistance in accordance with the policy on the Role of the EPA Inspector in Providing Compliance Assistance During Inspections? Yes

Comments:

| ICDS Sign Off | Name of Person | Date |
|-------------------------------|----------------|----------|
| ICDS Completed By: | pnenninger | 10/14/09 |
| ICDS Reviewed By: | | |
| ICDS ICIS Entry Completed By: | | |

Page 2 of 2 Last revised: 03/10/2006